

 1KBA-001	Campaign	
	Type: Recall or Special Service Campaign Area of Application: Europe Subject: Fuel pressure sensor. Models: IS250C; IS250 Model codes: GSE20	Engine

WHAT IS LEXUS GOING TO DO?

Owners of the involved vehicles will receive a campaign notification by first class mail. LEXUS retailers / authorized repairers will retighten the fuel pressure sensor to a specific torque, and if the fuel is leaking, replace the fuel pressure sensor gasket with a new one.

WHICH VEHICLES ARE INVOLVED?

Model Name	Model Code	VIN Range			Production Period
		WMI	VDS	VIS	
IS250	GSE20	JTH	BK262#	#2060448 - #2093907	August, 31 2007 through February, 3 2009
				#5052957 - #5097348	
IS250C	GSE20	JTH	FK252#	02500018 - 02500021	December, 5 2008 Through December, 8 2008

Note : # indicates that various characters may occupy that position.

IMPORTANT :

- Not all vehicles in these ranges are affected and/or sold in your country
- The detailed VIN-list of affected vehicles is available at your local Lexus retailers / authorized repairers

WHAT SHOULD AN OWNER DO IF THEY ARE CONCERNED ABOUT THIS CONDITION?

- Owners are requested to contact their local LEXUS retailer / authorized repairer for confirmation whether their vehicle is involved.
- Owners are requested to contact their local Lexus retailer / authorized repairer for diagnosis and repair.
- This Recall / Special Service Campaign will be performed at no cost by any LEXUS retailer / authorized repairer

WHEN WILL THIS RECALL / SPECIAL SERVICE CAMPAIGN EXPIRE?

This Recall / Special Service Campaign will be available at NO COST to the vehicle owners without time limitation.